

QUARTERLY PROGRESS REPORT FOR RERA BIHAR

Oct - Dec, 2020

ABSTRACT

This report documents and describes the updates on project work progress, with updates on status of financials, bookings in the project along with status of the approvals for the quarter.

PROJECT NAME

SAI VRINDAVAN GARDEN

PROMOTER NAME

AASTIK BUILDCON PVT. LTD.

RERA REGISTRATION NO.

BRERAP00098-7/417/R-275/2018

For AASTIK BUILDCON PVT. LTD.



Director

PROJECT QUARTERLY PROGRESS STATUS

Quarter: Oct-Dec, 2020

Project Description: *With pleasant surroundings and environmental cleanliness in abundance, this locality is best suited to get settled into. The project comprises of two residential towers (A & B) with B+LG+UG+7 and G+4floors respectively.*

Progress Update of each Block/Wing separately

Block A

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
1	Excavation	Yes	100%	Overall excavation works complete.
2	Foundation Works	Yes	85%	Half pile foundation and half raft foundation. Piling works complete and raft foundation works almost complete
3	Basement	Yes	0%	Activities yet to start.
4	Slabs of structure	Yes	0%	
5	Walls	Yes	0%	
6	Internal Plaster & Putty	Yes	0%	
7	Flooring inside units and common areas	Yes	0%	
8	Doors and Window to each of unit and common areas	Yes	0%	
9	Sanitary fittings within the unit including water proofing and plumbing	Yes	0%	
10	Electrical fitting within the unit	Yes	0%	
11	Staircase, lift walls and lobbies at each floor	Yes	0%	
12	Water tank	Yes	0%	
13	External Plumbing works and completion of terrace	Yes	0%	

For AASTIK BUILDCON PVT. LTD.

Page 1 of 8

Project Quarterly Progress Status - Sai Vrindavan Garden
Quarter Oct-Dec, 2020

[Signature]
Director

Progress Update of each Block/Wing separately

Block A

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
	with waterproofing of the building if specified.			
14	External Plaster	Yes	0%	
15	External Paint	Yes	0%	
16	Installation of lifts water pumps, firefighting fittings as NOC, Electricals fittings to the common areas, electro mechanic equipment, finishing to the entrance lobby, plinth protection, paving of areas, compound walls and other requirements as may be required to obtain completion/occupancy certificate. (Misc. Works)	Yes	0%	

For AASTIK BUILDCON PVT. LTD.

 Director

PROGRESS CHART (Block A)



For AASTIK BUILDCON PVT. LTD.

[Signature]
Director

Progress Update of each Block/Wing separately

Block B

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
1	Excavation	Yes	100%	Overall excavation works complete
2	Foundation Works	Yes	100%	Overall foundation works complete
3	Ground floor	Yes	0%	Activities yet to start.
4	Slabs of structure	Yes	0%	
5	Walls	Yes	0%	
6	Internal Plaster & Putty	Yes	0%	
7	Flooring inside units and common areas	Yes	0%	
8	Doors and Window to each of unit and common areas	Yes	0%	
9	Sanitary fittings within the unit including water proofing and plumbing	Yes	0%	
10	Electrical fitting within the unit	Yes	0%	
11	Staircase, lift walls and lobbies at each floor	Yes	0%	
12	Water tank	Yes	0%	
13	External Plumbing works and completion of terrace with waterproofing of the building if specified.	Yes	0%	
14	External Plaster	Yes	0%	
15	External Paint	Yes	0%	
16	Installation of lifts water pumps, firefighting fittings as NOC, Electricals fittings to the common areas, electro mechanic equipment, finishing to the entrance lobby, plinth protection, paving of areas, compound walls and other requirements as may be required to obtain completion/occupancy certificate. (Misc. Works)	Yes	0%	

PROGRESS CHART (Block B)											
	0%	10%	20%	30%	40%	50%	60%	70%	80%	90%	100%
Misc. Works											
External Plaster											
External Plastering works											
Water Tank											
Staircase, Lift Walls and Lobbies											
Electrical Fittings											
Sanitary Fittings											
Doors and Windows											
Flooring											
Internal Plaster and Putty											
Walls											
Slabs of Structure											
Ground floor											
Foundation Works											
Excavation											

Scope ■ Work Progress

For AASTK BUILDCON INT. LTD.
James W. R.
 Director

Progress Update for Common Areas, Facilities and Amenities in the Project

S. No.	Description	Applicable (Yes/No)	Percentage of Work Done	Remarks
1	Compound Walls	Yes	50%	Construction of compound walls complete. Finishing works yet to start
2	Water supply	Yes	40%	Boring works complete and supply pipes installation balance.

Update on number and types of flats/plots booked during the quarter for Block A & B

S.No	Unit Type	No. of Flats / Plot Booked				No. of Garages/ Covered Parking Booked			
		Opening Balance	Booked in the quarter	Cancelled in the quarter	Closing Balance	Opening Balance	Booked in the quarter	Cancelled in the quarter	Closing Balance
1	2BHK	2	0	0	2	2	0	0	2
2	3BHK	8	0	0	8	8	0	0	8

Status of financials in the project up to 30th September, 2020

S.No.	Description	Amount (in lacs Rs.)
1	Amounts received from allottees against booking of units(for builder's share)	13.93
2	Expenditure done towards completion of project	165.48
3	Balance in Designated Bank A/c as on this quarter end	Nil

Status of Approvals**A. Approval Received**

S. No.	Description	Date of Receipt
1	Airport Clearance	26.15.17
2	Sanctioning of Building Plan	16.02.18
3	RERA Registration	05.12.18

B. Approval Applied

S. No.	Description	Expected Date
NA	NA	NA

C. Approvals to be applied

S. No.	Description	Expected Date of application
NA	NA	NA

D. Modifications amendments or revisions, if any, issued by competent authority with regard to any sanctioned plans, layout plans, specifications, license, permit or approval for the project - NA

For AASTIK BUILDCON PVT. LTD.



Director

Project Site Photographs

