

QUARTERLY PROGRESS REPORT FOR RERA BIHAR

Jan–Mar,2021

ABSTRACT

This report documents and describes the updates on project work progress, with updates on status of financials, bookings in the project along with status of the approvals for the quarter.

PROJECT NAME

SAFFRONGARDEN

PROMOTER NAME

A & A ENGICONPVT. LTD.

RERA REGISTRATION NO.

BRERAP00235-1/914/R-663/2019

PROJECT QUARTERLY PROGRESS STATUS

Quarter: Jan–Mar, 2021

Project Description: A luxurious residential building project consisting of 2 Blocks, A Block consists of G+5F and Block B consists of B+G+5 Floors.

Progress Update of each Block/Wing separately

Block A

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
1	Excavation	Yes	100%	Over all Excavation works complete
2	Foundation Works	Yes	100%	Over all Piling works complete.
3	Ground Floor	Yes	99%	Over all ground floor works almost complete
4	Slabs of structure	Yes	100%	Over all Slab construction is complete.
5	Walls	Yes	100%	Over all brick work complete.
6	Internal Plaster & Putty	Yes	100%	Internal plaster and putty works has been completed On all floors.
7	Flooring inside units and common areas	Yes	100%	Over all flooring works complete.
8	Doors and Window to each of unit and common areas	Yes	100%	Door frames and door panels has been installed on each floors.
9	Sanitary fittings within the unit including waterproofing And plumbing	Yes	100%	Installation of WC and other fixtures complete on all Floors.
10	Electrical fitting within the unit	Yes	100%	Over all Electrical works completed.
11	Staircase, lift walls and lobbies at each floor	Yes	100%	Stair case structure, lift wall structure ,lobby structure Complete .Finishing works is completed.
12	Water tank	Yes	100%	Water tank structure and waterproofing complete.

Progress Update of each Block/Wing separately

Block A

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
13	External Plumbing works and completion of terrace With water proofing of the building if specified.	Yes	100%	External plumbing works & terrace waterproofing Complete.
14	External Plaster	Yes	100%	External Plastering works complete.
15	External Paint	Yes	50%	White wash done on all external side views.
16	Installation of lifts, water pumps, firefighting fittings as NOC, Electricals fittings to the common areas, electro mechanic equipment, finishing to the entrance lobby, plinth protection, paving of areas, compound walls and other requirements as may be required to obtain completion/occupancy certificate. (Misc. . .Works)	Yes	90%	Installation of fire-fighting pipes complete. Installation of water pumps complete. Lift installation works complete. Plinth protection works complete. Septic tank & soak pit works complete. Main gate works ongoing.

Progress Update of each Block/Wing separately

Block B

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
1	Excavation	Yes	100%	Over all excavation works complete.
2	Foundation Works	Yes	100%	Over all foundation works complete.
3	Basement	Yes	75%	Basement lift wall construction balance and finishing Works has been started.
4	Slabs of Structure	Yes	80%	5 th floorslab shuttering is completed and .Iron bar roof slab work is going on.
5	Walls	Yes	25%	Brickwork has been achieved till 3 rd floor
6	Internal Plaster & Putty	Yes	0%	
7	Flooring inside units and common areas	Yes	0%	
8	Doors and Window to each of unit and common areas	Yes	0%	
9	Sanitary fittings within the unit including waterproofing And plumbing	Yes	0%	
10	Electrical fitting within the unit	Yes	0%	
11	Staircase, lift walls and lobbies at each floor	Yes	57%	Stair case structure is complete up to 5 th floor
12	Water tank	Yes	0%	
13	External Plumbing works and completion of terrace With water proofing of the building if specified.	Yes	0%	
14	External Plaster	Yes	0%	
15	External Paint	Yes	0%	

Progress Update of each Block/Wing separately

Block B

S. No.	Task/Activity	Applicable (Yes/No)	Percentage of Work Done	Remarks
16	Installation of lifts water pumps, firefighting fittings as NOC, Electricals fittings to the common areas, electro mechanic equipment, finishing to the entrance lobby, plinth protection, paving of areas, compound walls and other requirements as may be required to obtain completion/occupancy certificate.(Misc. Works)	Yes	30%	Work on Progress as per Percentage.

Progress Update for Common Areas, Facilities and Amenities in the Project

S. No.	Description	Applicable (Yes/No)	Percentage of Work Done	Remarks
1	Compound Walls	Yes	90%	Brick work is almost completed.
2	Water supply	Yes	80%	Boring works and supply pipes installation-Complete in Block A and yet to start in Block B

Update on number and types of flats/plots booked during the quarter

S.No	Unit Type	Total No. of Unit sin builder's Share	No. of Flats/Plot Booked				No .of Garages/ Covered Parking Booked			
			Opening	Booked in the quarter	Cancelled in the quarter	Closing	Opening	Booked in the quarter	Cancelled in the quarter	Closing
1	2BHK	6	2	1	0	3	2	1	0	3
2	3BHK	17	15	2	0	17	15	17	0	17
3	4 BHK	1	1	0	0	1	1	0	0	1

Status of financials in the project up to 31stMarch, 2021

S. No	Description	Amount (in Rs.)
1	Amounts received from allot tees against booking of units(for builder's share)	5,68,95,647.00/-
2	Expenditure done towards completion of project	5,71,28,054.00/-
3	Balance in Designated Bank A/c as on this quarter end	2,02,490.00/-

Status of Approvals

A. Approval Received

S. No.	Description	Date of Receipt
1	Provisional fire clearance	17.07.12
2	Sanctioning of Building Plan	12.12.12
3	RERA Registration	14.06.19

B. Approval Applied

S. No.	Description	Expected Date
NA	NA	NA

C. Approvals to be applied

S. No.	Description	Expected Date of application
NA	NA	NA

D. Modifications amendments or revisions, if any, issued by competent authority with regard to any sanctioned plans, layout plans, specifications, license, permit or approval for the project - NA

Project Site Photographs

Block A





Project Quarterly Progress Status –Saffron Garden
Quarter Jan–Mar, 2021

Block B

